

# Welding Safety Video Series – Student Guided Notes

Name: \_\_\_\_\_ Date: \_\_\_\_\_

Directions: Watch each video carefully. Fill in the blanks, complete definitions, and answer short-response questions. Be prepared to discuss your answers in class.

## Module 1: Electric Shock

Contact with electrically “\_\_\_\_\_” parts can cause serious \_\_\_\_\_ or even \_\_\_\_\_.

Primary voltage shock comes from the \_\_\_\_\_ power supply.

Secondary voltage shock occurs at the welding \_\_\_\_\_.

The most common cause of shock is poor \_\_\_\_\_.

Moisture (like sweat, water, or damp clothing) \_\_\_\_\_ the risk of shock.

One way to avoid shock is to always keep your hands and gloves \_\_\_\_\_.

The video recommends placing the return clamp as \_\_\_\_\_ to the weld as possible.

If shock causes a fall, another possible injury could be \_\_\_\_\_.

Short Response: Explain why working in wet or damp areas is especially dangerous for welders.

## Module 2: Fumes & Gases

Welding fumes are tiny \_\_\_\_\_ that form when metals are heated above their boiling point.

Two common gases produced by welding are \_\_\_\_\_ and \_\_\_\_\_.

Breathing welding fumes may cause short-term effects like \_\_\_\_\_ and \_\_\_\_\_.

Long-term exposure can lead to serious \_\_\_\_\_ problems.

Good shop design includes proper \_\_\_\_\_ to remove fumes.

Ventilation works best when it pulls fumes \_\_\_\_\_ from the welder’s breathing zone.

When ventilation isn’t enough, welders should wear a \_\_\_\_\_.

Welding on metals with special coatings (like galvanized steel) can release toxic \_\_\_\_\_.

Short Response: Describe two ways you can tell if your ventilation is not working well.

## Module 3: Fire & Explosions

The welding arc can reach up to \_\_\_\_\_ °F.

Sparks can travel as far as \_\_\_\_\_ feet from the welding area.

Flammable materials include things like \_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_.

Compressed gas cylinders should always be stored \_\_\_\_\_ from heat and sparks.

Before welding, always check the area for possible \_\_\_\_\_ hazards.

Fire extinguishers should always be kept \_\_\_\_\_ to the welding area.

Hot metal can ignite a fire even \_\_\_\_\_ after welding has stopped.

Never weld near sealed \_\_\_\_\_ or \_\_\_\_\_, which could explode.

Short Response: If you had to weld near a wooden wall, what steps would you take to prevent fire?

## **Module 4: Miscellaneous Safety**

Warning labels and \_\_\_\_\_ must always be read and followed.

Confined spaces can have limited \_\_\_\_\_ and poor \_\_\_\_\_.

Always test the atmosphere in a confined space for \_\_\_\_\_ before welding.

Trailers or portable welders must be set up on a safe, \_\_\_\_\_ surface.

Welding machines must be properly \_\_\_\_\_ to avoid shocks or fires.

Damaged cords or leads can cause \_\_\_\_\_ and should be replaced immediately.

Always secure cylinders in an \_\_\_\_\_ position to prevent tipping.

Before welding, always inspect cables for \_\_\_\_\_ or \_\_\_\_\_.

Short Response: Why is grounding important for welding safety?

## **Module 5: Personal Protective Equipment (PPE)**

Arc rays can cause painful burns to the \_\_\_\_\_ and severe damage to the \_\_\_\_\_.

A welding helmet protects the \_\_\_\_\_ and \_\_\_\_\_.

Helmets must have the correct \_\_\_\_\_ shade to protect against arc rays.

Protective \_\_\_\_\_ and \_\_\_\_\_ keep your hands and arms safe from sparks.

Flame-resistant \_\_\_\_\_ and \_\_\_\_\_ should always be worn in the shop.

Shoes or boots should be made of \_\_\_\_\_ leather with \_\_\_\_\_ toes.

Ear protection helps prevent damage from \_\_\_\_\_ noise.

PPE must be inspected \_\_\_\_\_ and replaced when damaged.

Short Response: Which piece of PPE do you think is most important, and why?

## **Module 6: Cutting Systems**

Oxy-fuel cutting uses \_\_\_\_\_ and \_\_\_\_\_ gases.

Plasma cutting uses a stream of hot \_\_\_\_\_ to cut through metal.

Gas cylinders must always be stored and transported in an \_\_\_\_\_ position.

Always check hoses and \_\_\_\_\_ for leaks or damage before cutting.

Cylinders should be secured with a \_\_\_\_\_ to prevent tipping.

Sparks from cutting can travel farther than \_\_\_\_\_ feet.

CNC tables must never be operated without proper \_\_\_\_\_ in place.

Always shut off the gas supply when the system is not \_\_\_\_\_.

Short Response: What's one major difference between plasma cutting and oxy-fuel cutting?

## Final Reflection

Which video taught you something new you didn't know before?

\_\_\_\_\_

Which safety rule do you think is easiest for students to forget in the shop? \_\_\_\_\_

Write down one personal safety goal for this semester in the shop. \_\_\_\_\_